



**2008 Airbus EC135P2+ | #0649 | VT-AZY**





## TOTAL HOURS

3344.39 Hours Since New

## ENGINES

Pratt & Whitney PW206B2

#	S/N	Turbomachinery/RGB		
		TBO	TSO	Hrs Left
1	PCE-BJ0544	4000	2989.13	1010.47
2	PCE-BJ0543	4000	2792.02	1207.58

## HIGHLIGHTS

One Owner Since New

Weather Radar

LH Hoist Provisions

## AVIONICS

Dual VHF Com  
Dual VOR/ILS/GS  
Marker Receiver  
Automatic Direction Finder  
ATC Transponder  
Weather and Mapping Radar  
Radio Altimeter  
Intercom  
DME  
CVDR (Combi Unit)  
GPS  
Garmin GNS 430  
Garmin GNS 430  
Bendix King KR 21  
WULFSBURG DF-431B  
Garmin GTX 330  
Allied Signals RDR 2000  
Honeywell KRA 405B  
Becker AS 3100  
WULFSBURG DM-441B  
Honeywell AR 204C  
Garmin GNS 430

## EQUIPMENT

5 Passenger Corp Config  
Air conditioning System  
Sliding Windows in Sliding Doors (Crew)  
Dual Hinged Cockpit Doors with Sliding Window  
Dual Wide Passenger Sliding Doors  
Dual Rear Hinged Clam-shell Doors  
Co-Pilot's Instruments  
Central Panel Display System (CPDS)  
Vehicle and Engine Multifunction Display (VEMD)  
Cabin Fire Extinguisher  
Autopilot 3 Axis  
Emergency Flotation Gear Fixed Provision First Aid Kit  
Windshield Wiper System  
Dual Controls  
Search & Landing Light  
Standby Compass  
Anti - Collision Lights  
Artex E. L. T. 406 MHz

**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**







**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

**Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)**





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)





**2008 Airbus EC135P2+ | #0649 | VT-AZY**

Contact: William Sturm / +33 6 21 66 12 60 / [ws@aeroasset.com](mailto:ws@aeroasset.com)





# AEROASSET

[WWW.AEROASSET.COM](http://WWW.AEROASSET.COM)

Aero Asset / 181 Bay Street, Toronto, Canada M5J 2T9 / Phone: +1732 578 8217 / [sales@aeroasset.com](mailto:sales@aeroasset.com)

