



2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

©Copyright - AeroAsset, Inc © 2019 - All Rights Reserved • Specifications Subject To Verification upon Inspection.



PLAY VIDEO



TOTAL HOURS:
1822 Hours Since New

CYCLES: 6376

ENGINES:
Safran ARRIEL 2C2

#	TSN
ENG 1	1026
ENG 2	3964

HIGHLIGHTS

VIP 5/6 Pax Config

Air Conditioning

Enhanced Soundproofing

SBH/PBH Enrolled

Fresh 2 year / 600 hour Inspection (April 2019)

STANDARD AIRCRAFT IN ACCORDANCE WITH EC155 B1 06.100.01 E

EC155 B1 MINIMUM EQUIPMENT PACKAGE

Enhanced sound proofing (86 dB)

Avionics Package

Collins - VHF-AM - 422 A # 1

Crew headsets Silec 4449-1

Intercommunication system TEAM TB 31 with 2 CP 1976

Collins - VHF-AM - 422 A # 2

Transponder COLLINS TDR 94 D-007 with flight ident capability

Collins - ADF 462 #1

Collins - DME 442 - DME

VOR/ILS COLLINS VIR 432 (#1)

VOR/ILS COLLINS VIR 432 (#2)

Solid State Cockpit Voice & Flight Data Recorder HONEYWELL AR COMBI (2 hours CVR and 10 hours FDR recording)

UMS complement of SSCVFDR (Usage functions) Ground station excluded 2nd portable fire extinguisher

OPTIONAL EQUIPMENT

Customized outside paint

Air conditioning system (mechanically driven)

2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





TOTAL HOURS:
1822 Hours Since New

CYCLES: 6376

ENGINES:
Safran ARRIEL 2C2

#	TSN
ENG 1	1026
ENG 2	3964

HIGHLIGHTS

VIP 5/6 Pax Config

Air Conditioning

Enhanced Soundproofing

SBH/PBH Enrolled

Fresh 2 year / 600 hour Inspection (April 2019)

SPECIFIC MISSION EQUIPMENT

- Emergency floatation gear - Fixed parts
- Emergency floatation gear - Removable parts
- Emergency locator transmitter – KANNAD 406 AF
- Automatic voice alarm device RACAL V694 type
- Under fuselage anti-collision strobe light
- Mechanically Retractable Cabin Footsteps
- Hinged Cabin Doors

ADDITIONAL EQUIPMENT

- TAS RYAN 9900 BX (3 inch display)
- GPS FREEFLIGHT TNL 2101 I/O APPROACH + linked with ACFS and ND
- Moving map HONEYWELL KMD 850, linked with GPS
- Weather radar HONEYWELL RDR 2000 with VRU, displayed on ND
- Passengers address NAT AA 20-431 with 6 loudspeakers

INTERIOR LAYOUT

VIP 5/6 Pax interior comprising:

- 2 Captains Chars
- 3 / 4 Pax Bench Seating
- Carpeting in cockpit, cabin and luggage hold
- Leather cladding for additional upholstery
- Pilot's seats coverage in harmony with passenger seats coverage
- Pilots' and passengers' seats protection covers
- Cockpit and cabin floor protection covers
- Additional upholstery
- Passenger interphone for active noise cancelling headsets (BOSE) 1 x NAT AA-36 + 2 x NAT AA-82
- Active noise cancelling headset BOSE X

2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





2007 Airbus EC155B1 | S/N: 6771 | M-LIZI

Contact: William Sturm / +1 302 268 0189 / ws@aeroasset.com





WWW.AEROASSET.COM

Aero Asset / 181 Bay Street, Toronto, Canada M5J 2T9 / Phone: +1732 578 8217 / sales@aeroasset.com

