



2005 Leonardo A119K | #14502 | N119WG



PLAY VIDEO





TOTAL HOURS

4,956Hours Since New

ENGINE

Pratt & Whitney PT6B-37A
Engine enrolled on JSSI Maintenance Program

#	TSN
1	4,695

HIGHLIGHTS

Freshly Overhauled Engine

New Paint, Interior & Windscreen

Cargo Hook w/ Mirror

Inlet Filters

Enrolled on JSSI

AVIONICS

Garmin GNS 530 COMM/NAV/GPS with TIS traffic
King KY-196A COMM
Garmin GTX330 transponder
Bendix King KI-825 HSI/RMI
Two Agusta Electronic Display Units

OPTIONAL EQUIPMENT

Altair Avionics Engine Monitoring System
Dual controls with T/R pedal extension STC
Engine Inlet Barrier Filter System
Freon Air Conditioning
Fuel Flow Computer with Shadin Miniflo-L Display
Ground Handling Wheels
High Visibility Doors
LED Beacon/Landing/Taxi Lights
Lead Acid Battery STC
Medco Door Locks
Rotor Brake
Dual Stability Augmentation System with Forcetrain
Wire Strike Kit
Cargo hook with mirror

INTERIOR

Executive interior, 8 seats.
Rear six place club seating with tan leather and beige carpet.
Pilot and front passengers seats are covered with gray sheepskin.
Interior easily converts to utility configuration.

EXTERIOR

New paint May 2016.
Black upper, white lower with grey and gold accent stripes.

2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com





2005 Leonardo A119K | #14502 | N119WG

Contact: William Sturm / +33 6 21 66 12 60 / ws@aeroasset.com



PLAY VIDEO





WWW.AEROASSET.COM

Aero Asset / 181 Bay Street, Toronto, Canada M5J 2T9 / Phone: +1 732 578 8217 / sales@aeroasset.com

